Weathertzanton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW0354/1

Work Order Type: Weatherization

Audit Name: Audit-12012NW0354

CLIENT INFORMATION

Client Name: 12012NW0354 Address:

Client ID: 12012NW0354 , 38320

Alt. Client ID: Benton

CLIENT CONTACT INFORMATION

12012NW0354 Applicant/Person of

✓

Record

AGENCY INFORMATION

Agency: Northwest TN EDC Agency Phone: (731) 364-3228

Address: 231 S. Wilson Street Fax:

Dresden, TN 38225 *Email Address:*

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Client Name: 12012NW0354 Client ID: 12012NW0354 Alt. Client ID: Benton Work Order (Bid Form)
Work Order Name: WO/12012NW0354/1

Report Run On: 5/24/2010

DOE Weatherization Assistant Version 8.6.0

Page 1 of 5

Measures

Measure 1 Close Opening in Belly/Blanket and Reposition Falling Insulation						Componen		Inspected		
C	omment									
						Estimated	<u> </u>		Actual	
#	Material / Lal	bor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor				1					
2	Miscellaneo	us Su			1					
C	Other Detail							,		
					Measur	e Sub Total:]	Sub Total:	
	Field Notes:									

Measure 2 General Air Sealing Components Comment -Air seal around all windows, inside and outside -Air seal trim around all doors -Air seal duct penetrations through ceiling above air handler -Air seal around fireplace molding -Clear caulk door trim and seams in doorway on 1st and 2nd bedrooms on left (approx. 64 ft) -Clear caulk door trim from living room to kitchen (approx. 64 ft) -Air seal crown molding between dining room and living room at ceiling (approx. 9 ft) -Air seal vent cover over stove at crown molding at ceiling -Clear caulk top and bottom of crown molding at kitchen ceiling (approx. 88 ft)

					Estimated	1	Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing (setup cost)	Each	1					
10	Miscellaneous Su	Infiltration Reduction	Each	1					
C	Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								

Measure 3 Clean Blower and Coils (Evaporator and Condenser)			Component	ts		ı	Inspected	
Comment								
			Estimated	<u> </u>	Actual			
# Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Labor		1						
2 Heating Equipmen		1						
Other Detail	_							
		Measur	e Sub Total:			Sub Total:		
Measure 4 CO Monitor is Needed Comment			Component				Inspected	
Comment			Estimated			Actual	Inspected	
Comment # Material / Labor Description / Comment		Qty	-		Qty		Inspected	
Comment # Material / Labor Description / Comment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual		
Comment # Material / Labor Description / Comment			Estimated		Qty	Actual		
 Comment # Material / Labor Description / Comment 1 Health and Safety CO monitor 	Each	1	Estimated		Qty	Actual		
# Material / Labor Description / Comment Health and Safety CO monitor Labor	Each	1	Estimated		Qty	Actual		
# Material / Labor Description / Comment Health and Safety CO monitor Labor	Each Hour	1	Estimated			Actual		
# Material / Labor Description / Comment Health and Safety CO monitor Labor	Each Hour	1	Estimated Unit Cost			Actual Unit Cost		

Comment Include E	ace Return Filter (16 x	20)		Componen	ts		ı	Inspecte
John Midde L	.xara r moro			Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor			1					
2 Heating Equipmen			1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 6 Smol	ke Detector is Needed			Componen				Inspecte
				Estimated			Actual	
Material / LaborHealth and Safety	Description / Comment Smoke detector	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
Tleatti and Salety	Smoke detector	Lacii	'					
2 Labor	Labor	Hour	1					
Other Detail] [
] []		
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	